


2014 Annual Report

Minneapolis Heritage Preservation Commission



The Webster/Deinard Residence

1729 Morgan Avenue South

Construction: 1924 • Local Designation: September 19, 2014





City of Minneapolis

Mayor Betsy Hodges

Council President Barbara Johnson Council Vice President Elizabeth Glidden Council Majority Leader John Quincy Council Minority Leader Cam Gordon

> Council Member Lisa Bender Council Member Alondra Cano Council Member Jacob Frey Council Member Lisa Goodman Council Member Andrew Johnson Council Member Linea Palmisano Council Member Kevin Reich Council Member Abdi Warsame Council Member Blong Yang

This publication is the Annual Report for the Minneapolis Heritage Preservation Commission (HPC) for its fiscal year October 1, 2013-September 30, 2014. It has been prepared according to the guidelines outlined in "Procedures for **Applying For and Maintaining** Certified Local Government Status (CLG)." CLG status is administered by the Minnesota State Historic Preservation Office (SHPO) for the National Park Service. Each year, the HPC applies for CLG grants through the SHPO. An Annual Report is one of the requirements for maintaining CLG status.

Community Planning & Economic Department (CPED)

250 South 4th Street Minneapolis, MN 55415 www.minneapolismn.gov



Heritage Preservation Commission

Created in 1971, the Heritage Preservation Commission (HPC) is a 10-member commission comprised of persons living within the City of Minneapolis who possess a demonstrated interest, as well as professional experience and expertise, in preservation work.

2014 Heritage Preservation Commission Members

Laura Faucher, Chair Alex Haecker, Vice Chair Chris Hartnett, Secretary Paul Bengtson Susan Hunter Weir Ginny Lackovic Linda Mack Robert Mack Ian Stade Constance Vork

HPC Staff

Hilary Dvorak, Principal City Planner Hilary. Dvorak@minneapolismn.gov 612.673.2639.

Appointments

The HPC received one new first-term commissioner in January, Paul Bengtson, and confirmed the reappointments of three existing commissioners: Chris Hartnett, Ginny Lackovic, and Ian Stade.

Paul Bengtson was appointed to fill the vacancy created by the term limit of Chad Larson. Paul is a student completing a Master's of Science in Architecture: Heritage Conservation and Preservation at the University of Minnesota. With his Master's degree and over a decade of experience as a planner and having staffed boards and commissions in the past Paul is a huge asset to the HPC.

34rd Annual Statewide Historic Preservation Conference

The American Association for State and Local History held its 2014 National Conference in conjunction with the 34th Annual Statewide Historic Preservation Conference in Saint Paul, MN, September 17 through 20.

The following staff attended the conference: Andrew Liska and John Smoley. In addition to attending, Dr. Smoley presented a session titled "Bring Historic Preservation to our Community!"

Current Commissioner Chris Hartnett, HPC's 2014 Secretary, and Commissioner Ian Stade also attended the conference.

National Alliance of Preservation Commissioners (NAPC)

The Commission Assistance and Mentoring Program (CAMP) is NAPC's signature training program. Launched in the early 1990s, the program provides intensive, on-site training for local preservation commission members. Chris Hartnett, current commissioner and Minneapolis HPC's 2014 secretary, attended CAMP in Faribault, MN on August 22.

Minneapolis Heritage Preservation Awards

Co-sponsored between the HPC, the Minneapolis Chapter of the American Institute of Architects, and Preserve Minneapolis, the Preservation Awards recognize individuals and projects that promote and enhance heritage preservation in Minneapolis. The 23rd Annual Preservation Awards ceremony and luncheon was held on May 15, 2014, at the International Market Square.

Historic Restoration, Rehabilitation, or Adaptive Reuse Project

These are projects that return an existing place, property, building, or landscape to its original character in a manner that is respectful to the property's historic past, or which transform and reinvent the property to incorporate both new and old elements in a way that is respectful of yet different from the form of the past. The following projects received this honor:

- City Place Lofts
- Howe Community School Rehab
- Minneapolis Federal Office Building-Old Post Office
- Saint George Apartments

New Addition to an Historic Building

This category is intended for those where an addition was made to an existing place, property, building, or landscape in a manner that is respectful to the property's historic past.

 Hennepin County Library – Roosevelt

Single Family Residential

This category is intended to recognize and celebrate the hard work and serious efforts of any individual or team who has made a positive contribution to preserving, restoring, or rehabilitating a single family home anywhere in Minneapolis. The following projects received this honor:

- VMS Kaufmann House
- EJ Hansen, AIA Glass Art Project

Community Education and Advocacy

Meant to recognize organizations and their preservation-related education and outreach projects, there was one project from this category awarded this year. The following project received this honor:

• Hiding in Plain Sight Audio History Tour

Good Luck and Good Fortune

These are projects just getting started that have already committed to a specific preservation challenge in Minneapolis. This category is meant to encourage bold projects, draw attention to their high-minded purpose, and lend support through wider community knowledge of and participation in the project. The following projects received this honor:

 Growth with Preservation: Planning and Advocating for Dinkytown

The Steve Murray Award

The Steve Murray Award is considered the top individual honor for preservation in Minneapolis. It is awarded to an individual who has displayed leadership, courage, and dedication to heritage preservation in Minneapolis in the last year or over the course of his or her career or lifetime. The following individual received this honor:

• Sue Hunter Weir

Designation

Local Individual Designation

Webster/Deinard Residence

1729 Morgan Avenue South

Designation: September 19, 2014


The residence is a Tudor Revival style single family house of wood frame construction with exterior walls of half timbering framing panels of stucco and limestone details. It is eligible under Criterion #1 for its association with fair employment practices in Minneapolis, Criterion #2 for its association with Mr. Amos Samuel Deinard – attorney and civil rights supporter, Criterion #4 as it is an excellent example of the 1920s Tudor Revival Style, Criterion #5 for its integrated and intact landscape design, and Criterion #6 for its association with master architects Jacob Liebenberg and Seeman Kaplan.




Webster/Deinard Residence

CLG Grant

The City of Minneapolis was very pleased to have its FY 2014 \$14,978 certified local government grant application fully funded. The grant funds four designation studies of properties significant for their association with streetcar-related development.







Thomas Lowry Memorial



Camden Park State Bank



Northside Station



Hollywood Theater



Lake Harriet Methodist Episcopal Church



Arthur and Edith Lee House



Cameron Transfer and Storage Building



Plymouth Building

National Register of Historic Places Nominations

The HPC commented favorably on the following NRHP nominations:

Hollywood Theater

2815 Johnson Street Northeast

Eligible under Criterion A and under Criterion C for being a Liebenberg and Kaplan-designed Streamline Moderne neighborhood movie theater emblematic of the commercial patterns and trends of movie theater ownership and development in the years between World War One and World War Two, which saw theaters proliferate outside the central business district and within commercial nodes along streetcar lines.

Lake Harriet Methodist Episcopal Church

4401 Upton Avenue South

Eligible under Criterion C for its remarkable integrity of original materials and rarity of style in a primarily residential setting, as an ecclesiastical structure, make it unique among the existing Classical Revival buildings in Minneapolis.

Arthur and Edith Lee House

4600 Columbus Avenue South

Eligible under Criterion A for its association with the 1931 protests which took place at 4600 Columbus Avenue South, as well as with broader trends of housing discrimination in Minneapolis.

Cameron Transfer and Storage Building

756 Fourth Street North

Eligible under Criterion C for epitomizing the rapid evolution of structural design for warehouses in the first decade of the twentieth century from traditional timber building techniques honed over centuries to one reliant upon innovative engineering and the use of new materials, specifically through its use of both timber post-and-beam and reinforced-concrete mushroom-slab structural systems in the building.

Plymouth Building

12 Sixth Street South

Eligible under Criterion C in the area of engineering as a representation of the development and acceptance of reinforced-concrete skeleton frame construction by the American building industry.

Permits and Design Review

The Minneapolis Heritage Preservation Ordinance requires the HPC and CPED staff to review alterations to Landmarks, properties within historic districts, and properties under interim protection. Additionally, the ordinance requires CPED staff to review all wrecking and moving permits prior to issuance by the City to determine whether the affected property is a historic resource. If CPED staff determines that the property is a historic resource, the demolition requires approval by the HPC.

Certificates of Appropriateness

The HPC reviewed 33 Certificate of Appropriateness applications.

Historic Variances

The HPC reviewed and approved 13 Historic Variance applications.

Appeal of the Planning Director

The HPC did not review appeals of the Planning Director.

Demolition of Historic Resources

The HPC reviewed seven applications for the Demolition of a Historic Resource and approved two.

Certificates of No Change

CPED staff administratively reviewed 177 Certificate of No Change applications for minor alterations that did not change the historic integrity or visual character of the property.

Wrecking Permits

CPED reviewed and approved a total of 183 wrecking permits.

Heritage Preservation Files and Inventory

Community Planning and Economic Development (CPED) is located in room #300 of the Public Service Center Building, 250 South 4th Street, and retains Landmark nominations and survey forms for properties in the city as well as inventory files for designated districts and other potentially historic properties. Some of these materials are in survey form and typically contain brief descriptions of the resource or building, an approximate date of construction, a statement of significance, and a photograph. For locally designated properties, CPED maintains records on applications that have gone before the HPC for approval, as well as minutes from HPC meetings. There is also a collection of books maintained on the history of Minneapolis.

Research and Contacts

Survey and research information is available to the public during normal business hours. Those interested in researching any potential or known historic resources are encouraged to call for an appointment with CPED staff to discuss their specific needs or to view the HPC collection.

For more information or to schedule an appointment, contact HPC Committee Clerk Fatimat Porter, Fatimat.Porter@minneapolismn.gov 612.673.3153.

Certificates of Appropriateness – Public Hearing Items Reviewed from 10/1/2013 to 9/30/2014

No.	Date	Address	Designator	Туре	Outcome
1.	10/8/13	4291 Queen Ave S	Street Car Museum Landmark	Car barn	Approved
2.	10/22/13	3116 3rd Ave S	Bennett-McBride Landmark	Interior remodel & exterior modifications	Approved
3.	11/4/13	24 University Avenue NE	St. Anthony Falls	New 6-story, 56-unit residential building	Approved
4.	11/19/13	102 E 19th Street	Stevens Square	Doors and sidelights	Approved
5.	11/19/13	117 Portland Avenue S	St. Anthony Falls	Sign	Approved
6.	11/19/13	300 2 nd Street S	St. Anthony Falls	New apartment building and plaza	Approved
7.	11/19/13	101 3 rd Avenue S	St. Anthony Falls	New plaza and parking lot modifications	Approved
8.	12/10/13	212 2 nd Street SE	St. Anthony Falls	Exterior alterations	Approved
9.	12/10/13	1721 University Avenue SE	Greek Letter Chapter	Windows	Approved
10.	1/7/14	Franklin Avenue Bridge	Cappelen Memorial Bridge	Rehabilitation work	Approved
			Landmark		• •
11.	1/7/14	110 Bank Street SE	St. Anthony Falls	Mechanical equipment	Approved
12.	1/7/14	155 5 th Avenue S	St. Anthony Falls	Rooftop solarium/roof deck addition	Approved
13.	1/7/14	3112 3rd Avenue South	Healy Block	Windows	Approved
14.	2/18/14	24 University Avenue NE	St. Anthony Falls	Signs	Approved
15	3/18/14	300 Clifton Avenue	Eugene Carpenter House	Rooftop deck and exterior repairs	Approved
	, ,		Landmark		••
16.	4/1/14	100 3 rd Avenue SE	St. Anthony Falls	Sign rehabilitation	Approved
17.	4/1/14	500 3rd Street N	Warehouse	Addition and rehabilitation	Approved
18.	4/29/14	1612 Harmon Place	Harmon Place	Window replacement	Approved
19.	5/13/14	1612 Harmon Place	Harmon Place	Door replacement	Approved
20.	6/3/14	131 Oak Grove Street	Henry Ladd House Landmark	Detached garage	Approved
21.	6/17/14	510 1st Avenue N	Warehouse	Balcony	Approved
22.	6/17/14	194 Bank Street SE	St. Anthony Falls	Pergola install	Approved
23.	7/8/14	2400 Stevens avenue	Washburn Fair-Oaks	Remove retaining wall and porch rehab	Approved
24.	7/8/14	4901 Minnehaha Avenue	Minnehaha	Renovation of refectory	Approved
25.	7/22/14	1204 Harmon Place	Harmon	Rooftop deck	Approved
26.	7/22/14	150 Portland Avenue	St. Anthony Falls	Rooftop living space and deck	Approved
27.	8/5/14	1 (3) Lourdes Place	St. Anthony Falls	Up-lighting of the exterior	Approved
28.	8/5/14	21 3rd Street N	Warehouse	Masonry, doors and windows	Approved
29.	8/19/14	400 2nd Street SE	St. Anthony Falls	Exterior repair, windows, doors, HVAC	Approved
30.	8/19/14	428 2nd Street S	St. Anthony Falls	Allow a 5-story assisted living facility	Approved
31.	9/9/14	2412 1st Avenue S	Washburn Fair-Oaks	Rear porch	Approved
32.	9/23/14	241 1st Avenue N	Warehouse	Window replacement	Approved
33.	9/23/14	2300 Milwaukee Avenue	Milwaukee Avenue	Side porch	Approved

Historic Variances – Public Hearing Items Reviewed from 10/1/2013 to 9/30/2014

No.	Date	Address	Designator	Туре	Outcome
1.	10/8/13	4291 Queen Avenue S	Street Car Museum Landmark	Expansion of nonconforming use	Approved
2.	10/8/13	4291 Queen Avenue S	Street Car Museum Landmark	Develop within 40' of the top of a steep slope or bluff in the SH Overlay District	Approved
3.	10/8/13	4291 Queen Avenue S	Street Car Museum Landmark	Addition	Approved
4.	11/19/13	131 Oak Grove Street	Henry Ladd House Landmark	To allow use as a single-family dwelling	Approved
5.	3/18/14	300 Clifton Avenue	Eugene Carpenter Landmark	Exterior alterations	Approved
6.	3/18/14	300 Clifton Avenue	Eugene Carpenter Landmark	Permit bed and breakfast with more than three bedrooms available to guest	Approved
7.	3/18/14	300 Clifton Avenue	Eugene Carpenter Landmark	Reduce the required size of a mixed use building	Approved
8.	3/18/14	300 Clifton Avenue	Eugene Carpenter Landmark	Develop within 40' of the top of a steep slope or bluff in the SH Overlay District	Approved
9.	6/3/14	131 Oak Grove Street	Henry Ladd House Landmark	Install a detached garage over 12' in height w/o matching principal structure	Approved
10.	6/3/14	131 Oak Grove Street	Henry Ladd House Landmark	Install a detached garage within 40' of the top of a steep slope in the SH Overlay District.	Approved
11.	8/19/14	400 2nd Street SE	St. Anthony Falls	Install rooftop mechanical equipment	Approved
12.	8/19/14	400 2 nd Street SE	St. Anthony Falls	Adjust the number of required parking spaces	Approved
13.	9/9/14	2412 1st Avenue S	Washburn Fair-Oaks	Maintain existing side yard setback	Approved

Demolition of Historic Resources – Public Hearing Items

Reviewed from 10/1/2013 to 9/30/2014

No.	Date	Address	Designator	HPC Outcome	CC Outcome
1.	10/22/13	2309 W 53rd Street	Single-family dwelling	Approved	n/a
2.	11/19/13	4535 E Lake Harriet Pkwy	Single-family dwelling	Approved	n/a
3.	11/19/13	425 Portland Avenue S	Commercial building	Deny	Approved
4.	1/21/14	1319 4th Street SE	Commercial building	Deny	Denied
5.	1/21/14	1315 4th Street SE	Commercial building	Deny	Approved
6.	1/21/14	410 13th Avenue SE	Single-family dwelling	Deny	Approved
7.	3/18/14	2320 Colfax Avenue S	Boarding/rooming house	Deny	Approved

Certificates of No Change – Staff Approvals Reviewed from 10/1/2013 to 9/30/2014

No.	Date	Address	Designator (District)	Type (CNC)
1.	10/4/13	325 West River Pkwy #105	St. Anthony Falls	HVAC condenser and lines
2.	10/4/13	516 University Avenue SE	St Anthony Falls	Masonry
3.	10/4/13	1815 University Avenue SE	Greek Letter Chapter	Stucco
4.	10/8/13	900 3 rd Street N	Warehouse	Sign
5.	10/10/13	3101 2 nd Avenue S	Healy Block	Steps/buttresses work
6.	10/11/13	1901 Stevens Avenue	Stevens Square	Stone header and cornice
7.	10/17/13	2506 Stevens Avenue	Washburn Fair-Oaks	Roof
8.	10/17/13	3135 2 nd Avenue S	Healy Block	Handrail and window
9.	10/21/13	2500 Portland Ave S	Individual Landmark	Chimney
10.	10/21/13	2100 4th Avenue S	Washburn Fair-Oaks	Surface parking area accessory
11.	10/22/13	2103 Milwaukee Ave	Milwaukee Avenue	Basement finish
12.		248 & 252 1st Avenue N	Warehouse	Exterior paint
13.	10/25/13	301 Washington Avenue N	Warehouse	Signs
14.		401 8th Avenue SE	Fifth Street SE	Sign
15.	10/25/13	3124 3 rd Avenue S	Healy Block	Porch skirt
16.	10/25/13	206 Main Street	St. Anthony Falls	Roof
17.		800 Washington Ave N	Warehouse	Antennas
18.	11/1/13	500 3rd Street N	Warehouse	Windows
19.	, ,	2540 Park Avenue S	Individual Landmark	Sign
20.	11/4/13	1200 2 nd Avenue S	Individual Landmark	Masonry
21.		1200 2 Hvende S	Individual Landmark	Roof
22.		347 36th Street E	Individual Landmark	Chimney
23.		1128 Harmon Place	Harmon Place	Cellular antennas
24.	11/5/13	201 E Hennepin Avenue	St. Anthony Falls	Sign
25.	11/5/13	2519 1st Avenue S	Washburn Fair-Oaks	Rooftop bath vents
26.		101 5th Street S	Individual Landmark	Windows
27.	, ,	350 S 5th Street	Individual Landmark	Roof
28.	11/14/13	3954 Bryant Avenue S	Individual Landmark	Radon mitigation
20. 29.		2506 1st Avenue S	Warehouse	Roof
30.	11/15/13	800 Washington Avenue N	Warehouse	HVAC
31.		514 3rd Street N	Warehouse	Dryer vent
32.		212 2nd Street SE	St. Anthony Falls	Decking and railing
33.		618 Washington Avenue N	Warehouse	Vent gas fireplace
34.	11/18/13	209 Washington Avenue N	Warehouse	Wall sign
35.	11/10/13	800 Washington Avenue N	Warehouse	Rooftop fence
36.	11/20/13	337 Washington Avenue N	Warehouse	
36. 37.		207 Washington Avenue N		Sign Wall sign
37. 38.	11/22/13 12/5/13	105 1st Street N	Warehouse St. Anthony Falls	waii sign Rooftop a/c condenser
38. 39.		2406 Stevens Avenue S	Washburn Fair-Oaks	Carriage house roof
39. 40.	12/5/13		St. Anthony Falls	Screen porch windows
40. 41.		522 River Street 333 Washington Avenue N	Warehouse	Monument sign
	, ,	<u> </u>		Safety barriers
42.	, , -	1403 Harmon Place	Individual Landmark	
43.	12/15/13	750 2 nd Street S	St. Anthony Falls	Planting grates and trees
44.	12/16/13	217-219 3 rd Avenue N	Warehouse	Rooftop make-up air unit
45.	12/17/13	307 16 th Avenue SE	Greek Letter Chapter	Windows and bath fan
46.	12/30/13	West River Parkway	St. Anthony Falls	Trail improvements

47.	12/31/13	275 Market Street	Individual Landmark	Cellular antennas
48.	1/2/14	505 8 th Avenue SE	Fifth Street SE	Rear stairway
49.	1/8/14	219 2 nd Street N	Warehouse	Roof work and HVAC
50.	1/13/14	520 2nd Street SE	St. Anthony Falls	Wall sign
51.	1/14/14	600 Washington Avenue N	Warehouse	Sign
52.	1/21/14	106-108 Washington Avenue N	Warehouse	Rooftop HVAC
53.	2/6/14	133 1st Avenue N/ 28 2nd Street N	St. Anthony Falls	Window repair
54.	2/12/14	2200 Park Avenue	Individual Landmark	Window repairs and interior work
55.	2/14/14	333 Washington Avenue N	Warehouse	Projecting sign
56.	2/18/14	350 5th Street S	Individual Landmark	Cable outlet
57.	2/24/14	113 Washington Avenue N	Warehouse	Signs
58.	2/26/14	337 Washington Avenue N	Warehouse	Wall sign
59.	2/28/14	1300 Yale Place	Harmon Place	Siding
60.	3/4/14	1601 Hennepin Avenue	Harmon Place	Signs
61.	3/10/14	100 6 th Street N	Warehouse	Rooftop condensing unit
62.	3/7/14	730 Washington Avenue N	Warehouse	Wall sign
63.	3/10/14	1201 Hennepin Avenue	Harmon Place	Rooftop condensing unit
64.	3/12/14	1208 Harmon Place	Harmon Place	Temporary banner sign
65.	3/13/14	241 1st Avenue N	Warehouse	Window replacements
66.	3/17/14	901 Nicollet Mall	Individual Landmark	Cellular antennas
67.	3/24/14	1609 Hennepin Avenue	Harmon Place	Signs
68.	4/1/14	219 2 nd Street N	Warehouse	Rooftop condensing unit and fresh air vent
69.	4/9/14	401 8th Avenue SE	Fifth Street SE	Sign
70.	4/10/14	2925 Cedar Avenue S	Individual Landmark	Marker replacement
			Washburn Fair-Oaks	
71.	4/11/14	2501 Stevens Avenue 724 1st Street N		Rooftop fans
72.	4/16/14		St. Anthony Falls	Wall sign
73.	4/28/14	910 Hennepin Avenue S	Individual Landmark	Seats
74.	4/28/14	88 17th Street N	Individual Landmark	Fences, chiller
75.	4/29/14	88 17 th Street N	Individual Landmark	Dryer vent
76.	4/30/14	194 Bank Street	St. Anthony Falls	Pergola
77.	5/1/14	3116 3 rd Avenue S	Individual Landmark	Bathroom
78.	5/1/14	1717 (1725) 2 nd Avenue S	Stevens Square	Rooftop mechanical equipment
79.	5/1/14	110 Bank Street	St. Anthony Falls	Masonry repair
80.	5/8/14	300 1st Avenue N	Warehouse	Projecting sign
81.	5/8/14	424 3 rd Avenue N	Warehouse	Masonry repair
82.	5/8/14	211 Bank Street	St. Anthony Falls	Furnace and a/c
83.	5/8/14	168 Bank Street	St. Anthony Falls	A/C replacement
84.	5/8/14	3 2 nd Street SE	St. Anthony Falls	A/C replacement
85.	5/12/14	333 Washington Avenue N	Warehouse	Projecting sign
86.	5/12/14	15 1st Street S	St. Anthony Falls	Masonry repairs
		105 1st Avenue N		
87.	5/12/14		Warehouse Stevens Square	Reroof
88.	5/12/14			
		1717 2 nd Avenue S	•	Reroof
89.	5/12/14	420 5th Street N	Warehouse	Cellular antenna
90.	5/15/14	420 5 th Street N 212 (200) 3 rd Avenue N	Warehouse Warehouse	Cellular antenna Exterior repair
90. 91.	5/15/14 5/16/14	420 5 th Street N 212 (200) 3 rd Avenue N 1834 Emerson Avenue N	Warehouse Warehouse Individual Landmark	Cellular antenna Exterior repair Masonry repair
90. 91. 92.	5/15/14 5/16/14 5/16/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street	Warehouse Warehouse Individual Landmark St. Anthony Falls	Cellular antenna Exterior repair
90. 91.	5/15/14 5/16/14 5/16/14 5/16/14	420 5 th Street N 212 (200) 3 rd Avenue N 1834 Emerson Avenue N	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work
90. 91. 92.	5/15/14 5/16/14 5/16/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street	Warehouse Warehouse Individual Landmark St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement
90. 91. 92. 93.	5/15/14 5/16/14 5/16/14 5/16/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work
90. 91. 92. 93. 94.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement
90. 91. 92. 93. 94. 95.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent
90. 91. 92. 93. 94. 95. 96.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings
90. 91. 92. 93. 94. 95. 96.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition
90. 91. 92. 93. 94. 95. 96. 97. 98.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Fifth Street SE	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch
90. 91. 92. 93. 94. 95. 96. 97. 98. 99.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 6/2/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/4/14 6/4/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/4/14 6/4/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 401 5th Street SE 3406 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/4/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/4/14 6/4/14 6/4/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/4/14 6/9/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #710	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line
90. 91. 92. 93. 94. 95. 96. 97. 98. 100. 101. 102. 103. 104. 105. 106. 107. 108.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/9/14 6/9/14 6/9/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line
90. 91. 92. 93. 94. 95. 96. 97. 98. 100. 101. 102. 103. 104. 105. 106. 107. 108.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/4/14 6/9/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #710	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line
90. 91. 92. 93. 94. 95. 96. 97. 98. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/9/14 6/9/14 6/9/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #710 117 Portland Avenue S #302	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/4/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2rd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2rd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #302 750 2rd Street S	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls St. Anthony Falls St. Anthony Falls	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line A/C condenser replacement HVAC installation
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #302 750 2nd Street S 131 Oak Grove Street	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls Individual Landmark	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line A/C condenser replacement HVAC installation Roof repairs
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 111. 112.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #710 117 Portland Avenue S #302 750 2nd Street S 131 0ak Grove Street 131 0ak Grove Street	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls St. Anthony Falls St. Anthony Falls St. Anthony Falls Individual Landmark Individual Landmark	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line A/C condenser replacement HVAC installation Roof repairs Masonry repairs
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 111. 112. 113.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/4/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/9/14 6/10/14 6/18/14 6/23/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #710 117 Portland Avenue S #302 750 2nd Street S 131 Oak Grove Street 131 Oak Grove Street 1724 Kenwood Parkway 158 Bank Street	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls St. Anthony Falls St. Anthony Falls Individual Landmark Individual Landmark Individual Landmark Individual Landmark Individual Landmark Individual Landmark	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line A/C condenser replacement HVAC installation Roof repairs Masonry repairs HVAC replacement
90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 111. 112. 113. 114.	5/15/14 5/16/14 5/16/14 5/16/14 5/16/14 5/16/14 5/19/14 5/20/14 5/29/14 5/30/14 5/30/14 6/2/14 6/2/14 6/2/14 6/4/14 6/4/14 6/9/14	420 5th Street N 212 (200) 3rd Avenue N 1834 Emerson Avenue N 178 and 180 Bank Street 716 1st Street N 2103 2nd Avenue S 350 5th Street S 901 Nicollet Mall 400 4th Street S 100 2nd Avenue N 401 5th Street SE 218 Washington Avenue N 1821 University Avenue SE 401 5th Street SE 614 1st Street N 1129 University Avenue SE 3406 University Avenue SE 1601 University Avenue SE 525 3rd Street N #111 117 Portland Avenue S #710 117 Portland Avenue S #302 750 2nd Street S 131 0ak Grove Street 131 0ak Grove Street	Warehouse Warehouse Individual Landmark St. Anthony Falls Warehouse Washburn Fair-Oaks Individual Landmark Individual Landmark Individual Landmark Warehouse Fifth Street SE Warehouse Greek Letter Chapter Fifth Street SE St. Anthony Falls Greek Letter Chapter Potential Historic Resource Greek Letter Chapter Warehouse St. Anthony Falls St. Anthony Falls St. Anthony Falls St. Anthony Falls Individual Landmark Individual Landmark	Cellular antenna Exterior repair Masonry repair Decking replacement Roof work Masonry retaining wall replacement Vent Signs and awnings Vent Rehabilitation of rear addition Rehabilitation of front porch Signage Fire department key box installation Reroof Concrete replacement in rear of building Roof work Wall sign Masonry repairs Gas and water line installation Gas line Gas line A/C condenser replacement HVAC installation Roof repairs Masonry repairs

	6/26/14	337 Washington Avenue N	Warehouse	Temporary rooftop cellular antenna array
	6/27/14	101 5 th Street S	Individual Landmark	Awning installation
	6/27/14	275 Market Street	Individual Landmark	Wall sign
	6/27/14	126 Franklin Avenue E	Individual Landmark	Roof and scupper replacement
	7/2/14	2 Grove Street	St. Anthony Falls	HVAC replacement
	7/3/14	1415 4th Street SE	Potential Historic Resource	Wall sign
	7/3/14	70 2 nd Street S	St. Anthony Falls	Temporary stage
124.	7/11/14	516 University Avenue SE	St. Anthony Falls	Step removal
125.	7/11/14	1717 University Avenue SE	Greek Letter Chapter	Terrace masonry repairs
126.	7/16/14	97 Nicollet Street	St. Anthony Falls	Roof replacement
127.	7/17/14	708 1st Street N	Warehouse	Window replacements
128.	7/24/14	504 River Street	St. Anthony Falls	Door replacement
129.	7/24/14	102 3 rd Avenue NE	St. Anthony Falls	Reroof
130.	7/24/14	61 4 th Avenue N #102	St. Anthony Falls	A/C replacement
131.	7/24/14	400 1st Street N	St. Anthony Falls	A/C replacement
132.	7/24/14	615 1st Street N #406	St. Anthony Falls	Rooftop a/c condenser replacement
	7/24/14	910 Hennepin Avenue S	Individual Landmark	Rooftop a/c condenser replacement
	7/24/14	131 Oak Grove Street	Individual Landmark	Plumbing
	7/24/14	402 River Street	St. Anthony Falls	Deck addition
	7/24/14	800 1st Street N	St. Anthony Falls	Masonry repair
	7/25/14	88 17 th Street N	Individual Landmark	Lights
	7/25/14	2300 Milwaukee Avenue	Milwaukee Avenue	Window replacements
	7/25/14	1200 2 nd Avenue S	Individual Landmark	Masonry repair
	7/28/14	1605 Hennepin Avenue	Harmon Place	Wall cap
	7/30/14	2225 East Lake of the Isles Parkway	Individual Landmark	Patio/deck
	7/31/14	123 3rd Street N	Warehouse	Cellular antennas
	8/1/14	2105 1st Avenue S	Washburn Fair-Oaks	Rooftop a/c condenser replacement
	8/1/14	2301 Milwaukee Avenue	Milwaukee Avenue	Storm window replacements
	8/1/14	1615 University Avenue SE	Greek Letter Chapter	Roof repairs
	8/1/14	400 1st Street N #406	St. Anthony Falls	Rooftop a/c condenser replacement
	8/5/14	217 5th Avenue N	Warehouse	Sign
	8/6/14	15 E Franklin Avenue #332	Washburn Fair-Oaks	Patio door
	8/7/14	27 Maple Place	St. Anthony Falls	Roof, gutters, doors, and driveway
	8/11/14	131 Oak Grove Street	Individual Landmark	Rear addition, window and interior work
	8/14/14	1109 5th Street SE	Greek Letter Chapter	Chimney rebuild
152.		117 Portland Avenue	St. Anthony Falls	Tuck-pointing, brick replacement, concrete
	-//			patching
153.	8/15/14	424 3 rd Avenue N	Warehouse	A/C condenser units on the roof
	8/15/14	609 9th Street S	South Ninth Street	Window replacements
	8/15/14	300 Washington Avenue S	Individual Landmark	Rooftop equipment and screening
	8/18/14	212 1st Street N	Warehouse	Gas line
	8/18/14	2432 Stevens Avenue	Washburn Fair-Oaks	Reroof and skylight replacement
	8/21/14	20 University Avenue NE	St. Anthony Falls	Wall sign
	8/21/14	1603 Hennepin Avenue	Harmon Place	Signs
	8/21/14	1900 Stevens Avenue	Stevens Square	Window replacements
	8/22/14	102 19th Street E	Stevens Square	Landing alterations
	8/25/14	2707 ½ Lake Street E	Individual Landmark	Sign
	8/26/14	406 River Street	St. Anthony Falls	Replace a/c condenser
	8/26/14	40 Power Street	St. Anthony Falls	Replace a/c condenser and furnace
	8/26/14	620 1st Street N	Warehouse	Tuck-pointing and brick replacement
	8/29/14	1821 University Avenue SE	Greek Letter Chapter	Gutter replacement on front elevation
167.	9/9/14	221 1st Avenue NE	St. Anthony Falls	HVAC condenser replacement
	9/12/14	402 River Street	St. Anthony Falls	Deck addition
169.	9/15/14	350 5th Street S	Individual Landmark	Creation of two interior doorways
170.		2441 1st Avenue S	Washburn Fair-Oaks	Dryer vent
	9/23/14	43 Main Street SE	St. Anthony Falls	Projecting sign
171.	9/24/14	315-317 Washington Avenue N	Warehouse	Mural
	9/24/14	110 5th Street N	Warehouse	Projecting sign
173.	9/25/14	414 7 th Avenue SE	Fifth Street SE	Cellular antennas
174.	, ,	800 Washington Avenue N	Warehouse	Cellular antennas
175. 176.		327 5th Street SE	Fifth Street SE	Windows, doors, exterior and interior work
	9/29/14	405 14 th Avenue SE	Potential Historic Resource	Signs
1//.	1/41/14	IOU IT AVCHUCUL	i otentiai mistorie nesource	Jigiis